



# GMP 120.25

## INSTALLATION PLAN


FRONT






SIDE



TOP



## WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	31 Amps	18 Amps	12 Amps
Total power required	7,13 kW	7,13 kW	7,13 kW
Differential magnetothermal switch	Idn = 0.03 Amps	Idn = 0.03 Amps	Idn = 0.03 Amps
Ducting	n/a	n/a	n/a
Clearance around the ironer	back: not needed - right: 650 mm - left: not needed		