



G21.35

INSTALLATION PLAN

FRONT




TOP






INSTALLATION PLAN

SIDE



WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	n/a	71 Amps	41 Amps
Total power required	n/a	28 kW	28 kW
Differential magnetothermal switch	n/a	I _{dn} = 0.03 A	I _{dn} = 0.03 A
Ducting	n/a	Ø80 mm, 280 m ³ /h	Ø80 mm, 280 m ³ /h
Clearance around the ironer	back: 500 mm - right: 500 mm - left: 500 mm		